

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/16 to 31/03/17.	Visits completed for the period 01/04/16 to 31/10/16.
B & E Skips, 115 Brize Norton Road, Minster Lovell, Oxon, OX29 0SQ.	Minster Lovell	W	Active	Nil	1	3
Burford Quarry, Burford Road, Brize Norton, Oxfordshire.	Quarrying	M	Active	Full	3	1
	Manufacturing					
Castle Barn Quarry, Sarsden		M	Active	Full	2	1
City Farm, Eynsham.	City Farm I	W	Aftercare	Full	1	1
	New Wintle Farm	W	Active	Nil		
	City Farm II	W	Aftercare	Nil		
Controlled Reclamation, Dix Pit, Stanton Harcourt, Oxon.		W	Active	Full	3	4
Sheehan Recycled Aggregates, Dix Pit, Stanton Harcourt, Oxon.	Wash Plant	W	Active	Nil	2	2
Cornbury Park, (Quarrying) Charlbury, Oxon.		M	Active	Full	1	1

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/16 to 31/03/17.	Visits completed for the period 01/04/16 to 31/10/16.
Crawley Scrap Yard		W	Active	Nil	1	0
Deans Pit CA Site, Chadlington.		W	Closed	Nil	1	1
Dix Pit, Stanton Harcourt, Oxon.	Conblock	W	Dormant	Nil	3	2
	Dix Pit CA	W	Active	Nil		
	Dix Pit Landfill Site	W	Active	Full		
	North Shore	M	Complete	Full		
	Premix - Hanson	M		Nil		
Duns Tew Quarry		M	Active	Full	3	1
Elmwood Farm, Burford Road, Black Bourton, Oxon, OX18 2PL		W	Dormant	Nil	1	0
Enstone Airport Waste Transfer. Unit 1, Enstone Airfield, Enstone, Oxon.	Waste Transfer (Unit 1)	W	Active	Nil	1	2
	Sound Attenuation Bunds	W	Active	Full		
Ethos Waste Transfer Lakeside Industrial Estate, Standlake, Oxon		W	Dormant	Nil	1	0

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/16 to 31/03/17.	Visits completed for the period 01/04/16 to 31/10/16.
Fraser Evans & Sons, Worsham Quarry, Minster Lovell, Oxon.	Tyre Recycling	W	Active	Nil	1	1
	Landfill	W	Aftercare	Full		
Gill Mill, Tar Farm, Gill Mill Complex, Ducklington, Oxfordshire.	Rushey Common	M	Aftercare	Full	4	2
	Gill Mill Quarry	M	Active	Full		
Great Tew Quarry, Butchers Hill, Great Tew, Oxon.		M	Active	Full	8	3
Hardwick Batching Plant, Adj. B4449, Hardwick, Oxon.	CEMEX	M	Active	Nil	1	0
Hardwick Recycling, Adj. B4449, Hardwick, Oxon.	Fergal Yard	W	Active	Nil	1	0
Hickman Bros Landscapes, Burford		W	Active	Nil	1	0
Alder & Allen, Lakeside Industrial Estate, Standlake		W	Active	Nil	1	0

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/16 to 31/03/17.	Visits completed for the period 01/04/16 to 31/10/16.
Manor Farm - Waste Transfer, Kelmscott, GL7 3HJ.		W	Active	Nil	1	1
May Gurney, Downs Road WTS, Witney, Oxon.		W	Active	Nil	2	1
Mick's Skips (Hackett's Yard), Lakeside Industrial Estate, Standlake, Oxon.		W	Active	Nil	1	0
Sandfields Farm, Over Norton, Oxfordshire.		W	Active	Nil	1	1
Rollright Quarry, Chipping Norton.	Phase 1	M	Active	Full	2	1
	Phase 2	M	Active	Full		
Showell Farm, Chipping Norton, Oxon OX7 5TH.		W	Active	Nil	1	1
Slope Hill Quarry, Glympton.		W	Active	Nil	2	1
Old Railway Halt, Grt Rollright		W	Active	Nil	1	0
Old Quarry, Hatching Lane, Leafield		W	Active	Nil	1	1

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/16 to 31/03/17.	Visits completed for the period 01/04/16 to 31/10/16.
Hardwick IDO		M	ROMP	Low	0	0
Steve Claridge Motor Salvage, Carterton		W	Active	Nil	1	0
Sturt Farm, Units 2A, 4 Sturt Farm Ind, Burford.		W	Active	Nil	1	1
Watkins Farm, Linch Hill, Stanton Harcourt, OXON. OX29 5BJ.	ROMP area	M	Aftercare	Full	1	2
	Stonehenge Farm	M	Dormant – Small Scale Start	Full		
	Ireland Land	M	Dormant	Full		
Whitehill Quarry, Adj. A40, Burford, OXON.		M	Active	Low	1	0
Whitehill Quarry, Tackley, OXON.		M	Dormant	Low	1	0
Worton Rectory Farm, Cassington, OXON. OX29 4SU.	Cassington Quarry	M	Active	Full	4	4
	Worton Composting	W	Active	Nil		
	M&M WTS	W	Active	Nil		