

Minerals & Waste Compliance Monitoring Sites in South Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/18 to 31/03/19.	Visits completed for the period 01/04/18 to 31/10/18.
Ambrose Quarry, Ewelme, Oxon.		M	Dormant	Low	1	2
Battle Farm, Crowmarsh, Oxon, OX10 6SL.		W	Active	Nil	2	1
Caversham, Sonning Eye, Reading.	Caversham Main	M	Active	Full	5	3
	Caversham Triangle	M	In restoration	Full		
	Caversham Extension	M	Active	Full		
Chinnor Quarry.		M	Active	Full	1	0
Culham UKAEA		W	Active	Nil	0	0
Ewelme Landfill. Goulds Grove, Ewelme, Wallingford, Oxon.	Ewelme I (Buildings)	W	Active	Nil	3	2
	Ewelme I WTS	W	Active	Nil		
	Ewelme II MRF	W	Active	Nil		
	Ewelme II Landfill	W	Active	Full		
Eyres Lane Waste Transfer Site, Ewelme.		W	Active	Nil	2	1

Minerals & Waste Compliance Monitoring Sites in South Oxfordshire District.**Contact Officer : Chris Hodgkinson, Senior Planning Enforcement Officer.****Tel: 07899 065518**

Address	Sites	Type - Mineral or Waste.	Status	Charge	Target Visits for year 01/04/18 to 31/03/19.	Visits completed for the period 01/04/18 to 31/10/18.
Greenwoods of Garsington, Scrap Yard, Pettiwell, Garsington, Oxford.		W	Active	Nil	2	0
Main's Motors Ltd, Woodside, Old Henley Road, Ewelme, Oxon		W	Active	Nil	1	0
Hundridge Farm, Waste Transfer, Hundridge Farm, Ipsden, Oxon		W	Active	Nil	1	0
Menlo Industrial Park - Scrap Yard, Roycote Lane, Thame, Oxfordshire, OX9 2JB.		W	Active	Nil	1	0
Moorend Lane, Thame		M & W	Active	Full	3	1
Oakley Wood, Old Icknield Way, Crowmarsh		W	Aftercare	Nil	1	1
Playhatch Quarry - WTS, Dunsden Green Lane, Playhatch, Caversham, Reading.		W	Active	Nil	2	1
Woodeaton Quarry, Woodeaton, OXON.		M	Active	Full	3	3