

Minerals & Waste Compliance Monitoring Sites in Cherwell District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Alkerton CA & Landfill, Alkerton, Nr. Banbury, Oxon.	Alkerton Landfill	W	Aftercare	Full	1	1
	Alkerton CA	W	Active	Nil		
Barford Road Farm, Barford Road, South Newington, Banbury OX15 4JJ		W	Active	Nil	1	1
Hornton Grounds, Stratford Road, Hornton, Banbury, OX15 6AH.	Alkerton Quarry	M	Active	Full	3	2
	Hornton Grounds Quarry.	M	Active for stone processing			
	Wroxton	M	Active	Full		
Ardley Quarry, Ardley, Bicester, Oxon, OX27 7PH.	Ardley Landfill	W	Active	Full	3	2
	Ardley EfW	W	Active	Nil		
	Ardley Quarry	M	Active	Full		

Minerals & Waste Compliance Monitoring Sites in Cherwell District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Ardley Composting Site, Ashgrove Farm, Upper Heyford Road, Ardley, OX27 7PJ.	In-vessel Composting	W	Active	Nil	1	1
Belle Isle Farm, Sibford Road, Hook Norton		W	Active	Nil	1	1
Dewar's Farm, Ardley Road, Middleton Stoney.		M	Active	Full	3	3
Horsehay Quarry, Middle Barton Road, Duns Tew.		M	Active	Full	3	3
Ferris Hill Farm, Sibford Road, Hook Norton, Banbury, OX15 5JY.		W	Active	Nil	4	2
Finmere Quarry, Banbury Road, Finmere, Oxfordshire, MK18 4AJ.	Finmere (Landfill)	W	Active	Full	4	3
	Widmore	W	Aftercare	Nil		
	MRF	W	Dormant	Nil		
	Sand & Gravel	M	Not Implemented	Full		
Greenhill Farm Quarry, Bletchingdon.		W	Aftercare	Full	1	1

Minerals & Waste Compliance Monitoring Sites in Cherwell District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31//20
Heneff Way - Batching, Heneff Way, Banbury.		M	Active	Nil	1	1
Heneff Way - Tarmac, Heneff Way, Banbury.		M	Active	Nil	1	1
L.C. Hughes Scrap Yard, London Road, Bicester.		W	Active	Nil	1	1
Spittle Farm WTS, Thorpe Road, Overthorpe Industrial Estate, Banbury		W	Active	Nil	2	2
Shipton on Cherwell Quarry, Shipton on Cherwell, Oxfordshire.		W	Active	Full	4	3
Smiths of Bloxham - WTS. Milton Road, Bloxham, Banbury.		W	Active	Nil	2	0
Stratton Audley, Elm Farm Quarry, Stratton Audley.	Landfill	W	Dormant	Low	1	1
White Hill Quarry, Tackley, OXON		M	Dormant	Low	1	0
Cherwell Total	-	-	-	-	38	29 (76%)

Minerals & Waste Compliance Monitoring Sites in Oxford City

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Jackdaw Lane Scrap Yard		W	Active	Nil	1	1
Redbridge CA, Old Abingdon Road, Oxford.		W	Active	Nil	1	1
Oxford City Total	-	-	-	-	2	2 (100%)

Minerals & Waste Compliance Monitoring Sites in South Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/19
Ambrose Quarry, Ewelme, Oxon.		M	Dormant	Low	1	1
Battle Farm, Crowmarsh, Oxon, OX10 6SL.		W	Active	Nil	1	1
Caversham, Sonning Eye, Reading.	Caversham Main	M	Active	Full	3	2
	Caversham Triangle	M	In restoration	Full		
	Caversham Extension	M	Active	Full		
Chinnor Quarry.		M	Active	Full	1	2
Culham UKAEA		W	Active	Nil	0	0
Culham No 1		W	Active	Nil	0	1
Ewelme Landfill. Goulds Grove, Ewelme, Wallingford, Oxon.	Ewelme I (Buildings)	W	Active	Nil	3	2
	Ewelme I WTS	W	Active	Nil		
	Ewelme II MRF	W	Active	Nil		
	Ewelme II Landfill	W	Active	Full		
Eyres Lane Waste Transfer Site, Ewelme.		W	Active	Nil	2	3

Minerals & Waste Compliance Monitoring Sites in South Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Greenwoods of Garsington, Scrap Yard, Pettiwell, Garsington, Oxford.		W	Active	Nil	2	1
Main's Motors Ltd, Woodside, Old Henley Road, Ewelme, Oxon		W	Active	Nil	1	1
Hundridge Farm, Waste Transfer, Hundridge Farm, Ipsden, Oxon		W	Active	Nil	1	0
Menlo Industrial Park - Scrap Yard, Roycote Lane, Thame, Oxfordshire, OX9 2JB.		W	Active	Nil	1	1
Moorend Lane, Thame		M & W	Active	Full	3	2
New Barn Farm		M	Active	Full	4	5
Oakley Wood, Old Icknield Way, Crowmarsh		W	Aftercare	Nil	1	1
Playhatch Quarry - WTS, Dunsden Green Lane, Playhatch, Caversham, Reading.		W	Active	Nil	1	1

Minerals & Waste Compliance Monitoring Sites in South Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Woodeaton Quarry, Woodeaton, OXON.		M	Active	Full	3	3
South Oxfordshire Total	-	-	-	-	28	28 (100%)

Minerals & Waste Compliance Monitoring Sites in Vale of White Horse District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Aasvogel, Waste Transfer Station, Grove Business Park, Grove.		W	Active	Nil	1	0
Bowling Green Farm, Stanford Road, Faringdon, Oxon.		M	Active	Full	3	3
Childrey Quarry, Childrey, Wantage, Oxon.		W	Active	Full	1	2
Prospect Farm, Chilton, Didcot, Oxfordshire, OX11 0ST.		W	Active	Full	2	2
Drayton CA Site, Drayton, Oxon.		W	Active	Nil	1	1
Composting Facility, Church Lane, Coleshill, Swindon, SN6 7PR.		W	Active	Nil	1	1
Farringdon Quarry, Fernham Road, Little Coxwell, Oxfordshire.		M	Active	Full	2	2

Minerals & Waste Compliance Monitoring Sites in Vale of White Horse District

**Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386**

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Glebe Farm Composting, Glebe Farm, Hinton Waldrist, Oxfordshire.		W	Active	Nil	1	3
Haynes of Challow, East Challow, Wantage, Oxon, OX12 9TB.		W	Active	Nil	1	1
Hatford Quarry, Sandy Lane, Hatford, Oxon, SN7 8JH.		M	Active	Full	3	3
Hill Farm - Woodchipping, Nr Didcot, Oxfordshire.		W	Active	Nil	2	1
Quelchs Orchard, Scrap Yard, Charlton, Wantage.		W	Active	Nil	1	0
Radley Sand and Gravel Plant, Thrupp Lane, Radley.	Curtis Yard & Tuckwell's Plant	M & W	Dormant	Nil	1	1

Minerals & Waste Compliance Monitoring Sites in Vale of White Horse District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Harwell, UKAE, Harwell, Didcot, OX11 ORA.					0	0
	Business Park		Active	Nil		
	Catapult Pit		Active	Nil		
	Southern Storage		Active	Nil		
	Waste Management Complex (B462)	W	Active	Nil		
	Western Storage		Active	Nil	1	1
Radley Ash Disposal Scheme	Lake E	W	Not Implemented	Nil		
	Phase I	W	Aftercare	Full		
	Phase II	W	Aftercare	Full		
	ROMP area	M	ROMP	Full	1	1
Sandhill Quarry, Sands Hill, Faringdon, Oxon, SN7 7PQ.		M	Dormant	Low		
Shellingford Quarry, Shellingford Crossroads, Stanford In The Vale, Faringdon, Oxon, SN7 8HE.		W	Active	Full	3	4

Minerals & Waste Compliance Monitoring Sites in Vale of White Horse District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Stanford in the Vale Waste Disposal and Civic Amenity Site		W	Active	Nil	1	1
Stone Pitt Barn, Kingston Road, Frilford, Abingdon, OX13 5HB		W	Active	Nil	1	0
Sutton Courtenay (Hanson), Appleford Sidings, Abingdon, Oxfordshire, OX14 4PW.	Batching Plant	W	Active	Nil	4	4
	Bridge Farm	W	Active	Full		
	Rail Head	W	Active	Nil		
	Tarmac plant	W	Active	Nil		
Sutton Courtenay (FCC), Appleford Sidings, Abingdon, Oxfordshire, OX14 4PW.	Composting	W	Active	Nil	4	2
	Landfill	W	Active	Full		
Sutton Wick Landfill, Bassett Lane, Oday Hill, Abingdon.		W	Aftercare	Full	1	1
Sutton Wick Sand and Gravel, Peep-O-Day Lane, Abingdon, Oxon.	Allen Land	M	Restoration	Full	3	3
	Sutton Wick Plant	M	Active	Nil		
	CAMAS	M	Active	Full		

Minerals & Waste Compliance Monitoring Sites in Vale of White Horse District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Swannybrook Farm, Kingston Bagpuize		W	Active	Nil	2	1
Tubney Woods Sand Quarry and Landfill Site, Besselsleigh, Oxfordshire.		M	Restoration	Full	1	1
Upwood Park Sand Quarry and Landfill Site, Besselsleigh, Oxfordshire.		M	Active	Full	3	2
Whitecross Metals, Whitecross, Abingdon, Oxon.		W	Active	Nil	1	1
Wicklesham Quarry, Faringdon, Oxfordshire.		M	Aftercare	Full	2	2
Vale of White Horse Total	-	-	-	-	48	44 (91%)

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
B & E Skips, 115 Brize Norton Road, Minster Lovell, Oxon, OX29 0SQ.	Minster Lovell	W	Active	Nil	2	1
Burford Quarry, Burford Road, Brize Norton, Oxfordshire.	Quarrying	M	Active	Full	3	3
	Manufacturing					
Castle Barn Quarry, Sarsden		M	Active	Full	3	2
City Farm, Eynsham.	City Farm I	W	Aftercare	Full	1	1
	New Wintle Farm	W	Active	Nil		
		W	Aftercare	Nil		
New Wintle Farm		W	Non-active	Nil	3	5
Controlled Reclamation, Dix Pit, Stanton Harcourt, Oxon.		W	Active	Full	2	1
Sheehan Recycled Aggregates, Dix Pit, Stanton Harcourt, Oxon.	Wash Plant	W	Active	Nil	2	1
Cornbury Park, (Quarrying) Charlbury, Oxon.		M	Active	Full	1	1

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Crawley Scrap Yard		W	Active	Nil	1	1
Deans Pit CA Site, Chadlington.		W	Closed	Nil	1	1
Dix Pit, Stanton Harcourt, Oxon.	Conblock	W	Dormant	Nil	3	3
	Dix Pit CA	W	Active	Nil		
	Dix Pit Landfill Site	W	Active	Full		
	North Shore	M	Complete	Full		
	Premix - Hanson	M		Nil		
Enstone Airfield Waste Transfer. Unit 1, Enstone Airfield, Enstone, Oxon.	Waste Transfer (Unit 1)	W	Dormant	Nil	3	3
	Sound Attenuation Bunds	W	Active	Full		
Ethos Waste Transfer Lakeside Industrial Estate, Standlake, Oxon		W	Dormant	Nil	4	2

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Fraser Evans & Sons, Worsham Quarry, Minster Lovell, Oxon.	Tyre Recycling	W	Active	Nil	1	1
	Landfill	W	Aftercare	Full		
Worsham (Asthall)		W	Active	Nil	1	1
Gill Mill, Tar Farm, Gill Mill Complex, Ducklington, Oxfordshire.	Rushey Common	M	Aftercare	Full	3	2
	Gill Mill Quarry	M	Active	Full		
Great Tew Quarry, Butchers Hill, Great Tew, Oxon.		M	Active	Full	3	3
Hardwick Batching Plant, Adj. B4449, Hardwick, Oxon.	CEMEX	M	Active	Nil	2	1
Hardwick Recycling, Adj. B4449, Hardwick, Oxon.	Fergal Yard	W	Active	Nil	1	1
Hickman Bros Landscapes, Burford		W	Active	Nil	1	1
Alder & Allen, Lakeside Industrial Estate, Standlake		W	Active	Nil	1	1

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Manor Farm - Waste Transfer, Kelmscott, GL7 3HJ.		W	Active	Nil	1	1
Ubico, Downs Road WTS, Witney, Oxon.		W	Active	Nil	1	1
Mick's Skips (Hackett's Yard), Lakeside Industrial Estate, Standlake, Oxon.		W	Active	Nil	1	1
Mick`s Skips (Witney)		W	Active	Nil	1	1
Sandfields Farm, Over Norton, Oxfordshire.		W	Active	Nil	2	2
Rollright Quarry, Chipping Norton.	Phase 1	M	Active	Full	2	1
	Phase 2	M	Active	Full		
Showell Farm, Chipping Norton, Oxon OX7 5TH.		W	Active	Nil	1	1
Slope Hill Quarry, Glympton.		W	Active	Nil	2	3
Old Railway Halt, Grt Rollright		W	Active	Nil	1	1

Minerals & Waste Compliance Monitoring Sites in West Oxfordshire District

Contact Officers: David Periam, Interim Team Leader, David.Periam@Oxfordshire.gov.uk 07824 545378
 David Flavin, Principal Planning Officer, David.Flavin@Oxfordshire.gov.uk 07796 948386

Address	Sites	Type - Mineral or Waste	Status	Charge	Target Visits for year 01/04/19 to 31/03/20	Visits completed for the period 01/04/19 to 31/03/20
Steve Claridge Motor Salvage, Carterton		W	Active	Nil	1	1
Sturt Farm, Units 2A, 4 Sturt Farm Ind, Burford.		W	Active	Nil	1	1
Watkins Farm, Linch Hill, Stanton Harcourt, OXON. OX29 5BJ.	ROMP area	M	Aftercare	Full	3	3
	Stonehenge Farm	M	Dormant	Full		
	Ireland Land	M	Dormant	Full		
Whitehill Quarry, Adj. A40, Burford, OXON.		M	Active	Low	1	1
Worton Rectory Farm, Cassington, OXON. OX29 4SU.	Cassington Quarry	M	Active	Full	4	4
	Worton Composting	W	Active	Nil		
	M&M WTS	W	Active	Nil		
West Oxfordshire Total	-	-	-	-	63	59 (94%)
Oxfordshire Total	-	-	-	-	179	162 (91%)